

M10x1,25x30 - 6x
M10x25 - 2x
M12x30 - 4x
M12x90 - 2x (I)
M12x19 - 3x (C)
M12x21 - 1x (C)




M10 - 2x
M12 - 6x (I)
M12 - 4x (C)



PP10 - 8x
PP12 - 6x (I)
PP12 - 8x (C)

C



Galix®

